

# **TA-14**

Microphone windshield for TCIS / TCIV



### DESCRIPTION

Accessoire de protection contre le vent

The accessory allows placing Turbine Compact stations in windy areas and protects microphone against wind noise. This assures good audio intelligibility in difficult environments.


### Created: 27.06.2018, updated: 24.11.2020

www.zenitel.com

### info@zenitel.com

Zeritel and its subsidiaries assume no responsibility for any errors that may appear in this publication, or for damages arising from the information therein. Zeritel products are developed and marketed by Zeritel. The company's Quality Assurance System is certified to meet the requirements in NS-EN ISO 9001. Zeritel reserves the right to modify designs and alter specifications without notice.

# **TECHNICAL DIMENSIONS**



# USED WITH





1008111010 TCIS-1 IP and SIP Intercom

1008111020 TCIS-2 IP and SIP Intercom

1008111030 TCIS-3 IP and SIP Intercom

### Created: 27.06.2018, updated: 24.11.2020

# page 2/5

www.zenitel.com

info@zenitel.com

Zeritel and its subsidiaries assume no responsibility for any errors that may appear in this publication, or for damages arising from the information therein. Zeritel products are developed and marketed by Zeritel. The company's Quality Assurance System is certified to meet the requirements in NS-EN ISO 9001. Zeritel reserves the right to modify designs and alter specifications without notice.











TCIS-4 IP and SIP Intercom

# 1008111050

TCIS-5 IP and SIP Intercom

1008111060 TCIS-6 IP and SIP Intercom

1008114010 TCAS-1 Analog Intercom

1008114020 TCAS-2

### Created: 27.06.2018, updated: 24.11.2020

www.zenitel.com

page 3/5

### info@zenitel.com

Zeritel and its subsidiaries assume no responsibility for any errors that may appear in this publication, or for damages arising from the information therein. Zeritel products are developed and marketed by Zeritel. The company's Quality Assurance System is certified to meet the requirements in NS-EN ISO 9001. Zeritel reserves the right to modify designs and alter specifications without notice.



TCIV-2 Vandal Resistant VoIP Video Intercom

This product has been replaced by 1008315020 TCIV-2+



-

1008115030 TCIV-3 IP and SIP Video Intercom

This product has been replaced by 1008315030 TCIV-3+

### Created: 27.06.2018, updated: 24.11.2020

# page 4/5

www.zenitel.com

#### info@zenitel.com

Zeritel and its subsidiaries assume no responsibility for any errors that may appear in this publication, or for damages arising from the information therein. Zeritel products are developed and marketed by Zeritel. The company's Quality Assurance System is certified to meet the requirements in NS-EN ISO 9001. Zeritel reserves the right to modify designs and alter specifications without notice.





TCIV-6

IP and SIP Video Intercom

This product has been replaced by 1008315060 TCIV-6+



1008113020 TCIA-2 Analog over IP Intercom

### Created: 27.06.2018, updated: 24.11.2020

www.zenitel.com

#### info@zenitel.com

Zeritel and its subsidiaries assume no responsibility for any errors that may appear in this publication, or for damages arising from the information therein. Zeritel products are developed and marketed by Zeritel. The company's Quality Assurance System is certified to meet the requirements in NS-EN ISO 9001. Zeritel reserves the right to modify designs and alter specifications without notice.